


PJT122 Assembly Diagram

Parts List

No.	Name	Quantity	Unit
A	Table Top	1	PC
B	Table Leg	2	PCS



Hardware List

No.	Name	Size(mm)	Quantity	Unit
①	Screw	M8*40	8	PCS
②	Flat Washer	M8*20*2	8	PCS
③	Spring Washer	M8	8	PCS
④	Allen Key	Ø5mm	1	PC

Step 1

